



Robert Gretz
Senior Air Safety Investigator
Eastern Region Aviation

Date: **2/3/23**

Subject: **ERA23LA123**

Contact: **Robert Gonzalez Jr, FAA MCO FSDO**

Mr. Gonzalez was interviewed via telephone. He stated that he examined the wreckage yesterday at the accident site. Both wings were separated, and the fuselage sustained substantial damage. Mr. Gonzalez did not observe any preimpact mechanical malfunctions.