



Photo 1 – Digital Photograph From Williston Municipal Airport. Left Side View of the Inverted Airplane at the Accident Site.



Photo 2 - Digital Photograph From Williston Municipal Airport. Right Side View of the Inverted Airplane at the Accident Site.



Photo 3 – Screen Shot From FAA Movie. Left Aft Side of Misaligned Canopy with Fully Closed Canopy Handle.



Photo 4 – Screen Shot From FAA Movie. Right Aft Side of Canopy with Nearly Fully Closed Canopy Handle.




Photo 5 – Screen Shot From FAA Movie. View Showing Tooth of Canopy Handle Engaged with Canopy Latch.



Photo 6 – FAA Digital Photograph. View Showing the Fractured Forward Structure of the Vertical Stabilizer.