



NTSB ERA23LA165

Piper PA28-151, N541SP

Investigative Photographs



Photo 1: Overview of the airplane at the accident site (Photo Courtesy of FAA)



Photo 2: Overview of the airplane at the accident site (Photo Courtesy of FAA)



Photo 3: Overview of the underside of the fuselage at the accident site (Photo Courtesy of FAA)



Photo 4: Overview of the left wheel (Photo Courtesy of Florida Air Recovery)



Photo 5: Overview of the left main landing gear post-recovery (Photo Courtesy of Florida Air Recovery)



Photo 6: Overview of the right main landing gear post-recovery (Photo Courtesy of Florida Air Recovery)