

NTSB ERA23LA228

N62HT Robinson R44

Bradenton, Florida

Photo Array



Photo 1: View of helicopter on its right side.(Courtesy of FAA)



Photo 2: View of severed tail rotor assembly. (Courtesy of FAA)



Photo 3: View of helicopter and rotor mast up against dirt mound. (Courtesy of FAA)



Photo 4: Overall view of helicopter and debris field. (Courtesy of FAA)