

NTSB ERA23LA242

N105GS, Van's RV-9A

Photo Array



Photo 1: View of the airplane fuselage, vertical stabilizer and rudder damage (Photo Courtesy of FAA)



Photo 2: View of the damage to the vertical stabilizer and rudder (Photo Courtesy of FAA)