

ERA23LA293

AIRWORTHINESS

Specialist's Factual Report - Attachment 1

Record of clutch subassembly S/N 6968 installation onto N5027P, dated June 9, 2023

OPERATOR

NON-ROUTINE WORK CARD

N5027P



Model
MCDONNELL DOUGLAS 369D

Serial Number
611002D



Number	
20230609165607	
Reported Date	
09-Jun-2023	
ATA Chapter	Aircraft Grounded
	NO

MEL	NEF	CDL	MEL / NEF / CDL Code
Control Number		Status	
		Closed	

Description							
Remove and Replace O/R Clutch AD 90-19-02 inspection due.							
Notes							
Next Due Category	Next Due Date	Tracked By	Activation Date	Discrepancy Type	Delay Information	Discovery Point	Discovered By
		Airframe					
Next Due Hours	Next Due Cycles	Reported Hours	Reported Cycles	Preliminary Insp	Hidden Damage Insp	Action Code	Reference
		24799.30		NO	NO		

Hook Hrs 3604.5

Primary Information Entered By Name

Certificate Number

Date

Signature

Corrective Action Information

Complied With Date	C/W Hours	C/W Cycles	Work Hours	Interruption Hours	Resolved At	Resolved By
09-Jun-2023	24799.30	815891				

Notes	
Removed and Replaced O/R Clutch Old P/N 369A5350-51, S/N 56454761, with New P/N 369A5350-51, S/N 6968. Reference HMI-2, 63-10-00. Sprag S/N 10037 088 Sprag S/N 9870 1199.4 TSN @ this motor 1800 HZ Discard	

Christopher Rico
Technician Name

3562725
Certificate Number

09-Jun-2023
Date

Christopher Rico
Signature

[Handwritten signatures and markings]