

ERA23LA293

AIRWORTHINESS

Specialist's Factual Report - Attachment 3

Record of last overhaul of clutch subassembly S/N 6968, dated June 19, 2021



Haverfield Aviation Inc.

Task Card:

C00660-01

Department: 000031 Aircraft Maintenance Work Order: C00660 CLUTCH 6968

Task ID: 6310-150 OC OEM Ref.: HMI-2, 05-10-00 TABLE 1 DEPARTMENT
Description: Overhaul O/R Clutch sub assy.
ATA: 63-10-00 D/S,CLUTCH, COUPLINGS Pos. Path: 200: ORClutch • CL SUB ASSY
P/N: 369A5350-51 S/N: 6968 Descr: O/R CLUTCH SUB ASSY
Documents: ... Check: ...
Triggered by: ...

Skill Req.: ... Shop Est.: 0.00 H Created: 2021-05-10
Base: GBG Due At: ... DUE: ...

Task Description:

Overhaul O/R Clutch sub assy.

Corrective Action:

Overhauled clutch subassembly reference MDHI CSP COM 5, chapter 63-10-10, NDT completed by Power/Aviation, under P.O. 6860, on the following components, outer race P/N 369A5352-5, S/N 5034-0945, inner race P/N 369A5353-3, bearing carrier P/N 369A5355 (NOTE), replaced the following parts bearing P/N 369A5361, BN 27491, bearing P/N 369A5362, BN 25261, bearing P/N 369A5363, BN 25368, seal P/N 369A5368, BN 27493, packing (2ea) P/N M83248/1-026, BN 23805, packing P/N M83248/1-141, BN 27473, reference MDHI CSP COM 5

	Part Number	Serial Number	Description	Batch #
OFF				
ON				
OFF				
ON				

Date Completed: 2021-06-19	Flight Hours					
	2,891.70					

☐ Work complete	Signature: _____ License: _____ Date: _____
☐ Required Independent Inspection completed as per applicable maintenance standards.	Signature: _____ License: _____ Date: _____
☐ "The maintenance described above has been performed in accordance with the applicable standards of airworthiness."	Signature: _____ License: _____ Date: _____