


NATIONAL TRANSPORTATION SAFETY BOARD

ACCIDENT NUMBER:

RETENTION / RELEASE OF WRECKAGE RELATED TO ACCIDENT NUMBER ► ERA23LA310

For Use In All Modal Investigations

REGISTERED OWNER (name and address) STANLY BUSINESS CONSULTANTS LLC ALBERMARLE, NC 28001		IDENTIFICATION NUMBER N98134	
		MAKE Piper	
LOCATION New London, NC	DATE OF ACCIDENT 7/24/2023	MODEL PA-28-140	
RETAINED BY NTSB REPRESENTATIVE A. McCarter		TITLE ASI IIC	DATE 07/25/2023
The National Transportation Safety Board has ☒ has not ☐ completed its investigation of the wreckage described above. All recovered wreckage except that listed in the evidence control form(s) is hereby released. ☒ NO PARTS RETAINED			
RELEASED BY NTSB REPRESENTATIVE A. McCarter		TITLE ASI IIC	DATE 02/22/2024
(This section may be acknowledged by a person, not the owner or owner's representative, who has knowledge of the disposition of the recovered wreckage and its parts. Such acknowledgement does not place responsibility for disposition of the wreckage upon that person.) I HEREBY ACKNOWLEDGE: ☒ Receipt of the above described wreckage. ☐ Removal of the parts, if any, listed in the evidence control form(s).			
PERSON MAKING ACKNO Eric Weidner		TITLE Regional Manager	DATE 2/22/2024
ADDRESS Marietta GA		PHONE NUMBER & EMAIL  .com	
REMARKS: The entire airframe, engine and logbooks for aircraft N98134 has been released. The wreckage examination/investigation has concluded. 2/22/24 AM			