

Charles Cates

To: Lynn Spencer
Subject: ERA23LA363 (Frankfort, Ky) JPI EDM-800 Email Report
Attachments: IMG_0529.jpg; IMG_0531.jpg

Email Report

The Vehicle Recorder Division received a JPI EDM-800 (s/n 15260). The device was undamaged and powered on normally (IMG_0529.jpg and IMG_0531.jpg). Data recording is a user configurable option on this device, and it was configured to not record any data. Therefore, no data could be recovered from the device.

Prepared by: Charles Cates, Recorder Specialist, NTSB RE-40





EGT

CHT

500

400

300

OF

TIT

OIL

%

Limit

STEP

TSO

LeanFind

EDM



800

TSO C43b, Temperature Indicator Model EDM-700/800
P/N EGT-701-[6]C - O [] - A [4] - T [] - I [] - F [4] - R/M [.]
WT: 1.12 lbs, Volts: 11 to 30 VDC, TC: Type K
S/N 15260 MFG 9/01
SOFTWARE PN: 302661 - REV [2.8] S/W DO-178a, Level-3
DO-160C Env. Cat. B2YBA(MN)XXXXXXCBABATAXXX, Class 1b
Fuel Flow does not comply with TSO-C44
RPM Does not comply with TSO-49a
Manifold pressure does not comply with
J.P.INSTRUMENTS Inc, Box 7033 Huntington Bch CA 92646