

YEAR 20____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
------------------------	---------------------------	-------------------	-----------------------------	--

N81GX

Rotax 912ULS s/n 5651964

07/28/2023

TTSN: 2500

Performed annual condition inspection IAW Rotax 912ULS maint manual and Remos inspection checklist. Drained oil and replaced with 3L Aeroshell Sport plus 4 oil, removed and inspected magnetic oil plug, replaced oil filter w Rotax 925-016 filter. Replaced all spark plugs with NGK DCPR8E plugs and performed cold compression testall cylinders better than 78/80. Replaced #4 cylinder head. Carb sync checked ok. Test run-up satisfactory.

Aircraft returned to service.

Louis Cicalese AP [REDACTED]

YEAR 20____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
------------------------	---------------------------	-------------------	-----------------------------	--

YEAR 20____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
------------------------	---------------------------	-------------------	-----------------------------	--

N81GX

S/N 304

07/28/2023

TTAF: 2500

Performed annual airframe condition inspection IAW Remos maint manual. Elt batteries replaced, Due 07/28 Elt tested IAW Far 91.207D, satisfactory. Serviced aircraft battery, replaced forward muffler heat shie'd, serviced tires and checked brakes, lubed wheel bearings and all control surface hinge points. Propeller checked for damage, dressed minor dings. C/W Sb 513-001 cracks or damage in landing gear. No damage found.

Aircraft returned to service.

Louis Cicalese AP [REDACTED]

YEAR 20____ DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
------------------------	---------------------------	-------------------	-----------------------------	--

Thruway Coast Aviation, Inc.
3800 Saint Louis Blvd
FL Pierce, FL 34464
FAA CROE THE 888 TK
Serviceable Part

AIR: Garmin MODEL: GTX327 S/N: 83746349
A/C: N/A CUSTOMER: Cicalese
REPAIR: Fixed OK ☒ OK ☐ REPAIR ☐

THE COMPONENT IDENTIFIED ON THIS FORM WAS REPAIRED AND INSPECTED BY: [REDACTED] WITH CURRENT REGULATIONS OF THE FEDERAL AVIATION ADMINISTRATION AND IS APPROVED FOR RETURN TO SERVICE. PERTINENT DETAILS OF THIS REPAIR ARE ON FILE AT THIS REPAIR FACILITY UNIT.

WORK ORDER #: 12783
DATE: 08/07/23 INSPECTED BY: [REDACTED]