



MEMORANDUM FOR RECORD

Timothy W. Monville
Sr. Air Safety Investigator
Office of Aviation Safety-Eastern Region

Date: November 17, 2025

Subject: ERA24FA050

Contact: Video Camera Summary

Two video files without sound that captured the accident sequence of the airplane were provided to NTSB to assist with the investigation. The videos were taken from a video camera that was located about 4,000 ft northwest from the accident site location.

A 39 seconds long video labeled as "Lemons Hollow Video 1.mp4" and "CAM4", started with a displayed time of "05:47:55 PM". At 05:48:01 PM a white light was recorded in the upper left portion of the frame. The light continued to the right and ended with a large white light at 05:48:10 PM. The white light at the end which was consistent with impact continued in intensity of varying degree to the end of the recording.

A 44 seconds long video labeled as "CAM1", started with a displayed time of "05:47:51 PM". At 05:48:04 a white light was recorded in the left middle portion of the frame. The light continued to the right and ended with a large white light at 05:48:10 PM. The white light at the end which was consistent with impact continued in intensity of varying degree to the end of the recording.