



---

**Go Around: Two-Engine**

---

AFM Section IV

1. Thrust Levers..... MAX THRUST, OBSERVE N<sub>1</sub> AND ITT
2. Approach Climb Speed..... MAINTAIN  
(Press GA button and maintain a 9° deck angle minimum.)
3. GROUND A/B Switch ..... OFF
4. SLATS / FLAPS Lever..... 20°
5. Landing Gear Lever..... UP, AFTER ESTABLISHING  
POSITIVE CLIMB GRADIENT
6. T/R Switches ..... OFF (PRIOR TO REACHING 180 KIAS)  
(Verify both **ARM** lights extinguish.)
7. SLATS / FLAPS Lever..... UP AT 400 FT MINIMUM;  
ACCELERATE TO CLIMB SPEED

**END**