



Joshua Young
Air Safety Investigator
AS-ERA

Date: 5/2/2024

Subject: ERA24FA160, Adjustments to Carburetor

Contact: Chip Erwin, Manager, Aeromarine LSA

Mr. Erwin was contacted by the IIC on May 2, 2024, via electronic mail and asked the following question:

"Do you know of any adjustments made to the carburetor after the engine was received from the manufacturer?"

He replied the same day stating the following:

"The carb main jet was changed per advice from the USA Polini technician. All service bulletins were complied with."