

NATIONAL TRANSPORTATION SAFETY BOARD

NTSB Form 6120.1

PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

Email the pilot/operator aircraft accident/incident report to the investigator-in-charge of your accident/incident. If email is not available, mail the report per the instructions below.

If your accident/incident occurred in Maine, Vermont, New Hampshire, Massachusetts, Connecticut, Rhode Island, New York, New Jersey, Pennsylvania, Maryland, Delaware, Virginia, West Virginia, Kentucky, Tennessee, North Carolina, South Carolina, Mississippi, Alabama, Georgia, Florida, the District of Columbia, Puerto Rico, or the US Virgin Islands, send the form to: NTSB, ERA, 45065 Riverside Parkway, Ashburn, VA 20147.

If your accident/incident occurred in Ohio, Michigan, Indiana, Wisconsin, Illinois, Minnesota, Iowa, Missouri, Arkansas, Louisiana, North Dakota, South Dakota, Nebraska, Kansas, Oklahoma, Texas, Colorado, or New Mexico, send the form to: NTSB, CEN, 4760 Oakland Street, Suite 500, Denver, CO 80239.

If your accident/incident occurred in Montana, Wyoming, Idaho, Utah, Arizona, Nevada, Washington, Oregon, California, Hawaii, or the territories of Guam or American Samoa, send the form to: NTSB, WPR, 505 South 336th Street, Suite 540, Federal Way, WA 98003.

If your accident/incident occurred in Alaska, send the form to: NTSB, ANC, 222 West 7th Avenue, Room 216, Box 11, Anchorage, AK 99513.

Rules pertaining to notification of aircraft accidents and incidents, as well as overdue aircraft are found in 49 Code of Federal Regulations (CFR) Part 830 http://www.ecfr.gov/cgi-bin/text-idx?c=ecfr&tpl=/ecfrbrowse/Title49/49cfr830_main_02.tpl. These rules state the authority of the NTSB, define accidents, incidents, injuries, and other terms, and provide procedures for initial and immediate notification of accidents and incidents by aircraft pilots/operators.

A. APPLICABILITY

The pilot/operator of an aircraft shall send a report to the office listed above, based on accident/incident location; immediate notification is required by 49 CFR 830.5(a). **The report shall be filed within 10 days after an accident for which notification is required by Section 830.5, or after 7 days if an overdue aircraft is still missing.**

An aircraft accident, as defined in 49 CFR 830.2, is determined as an occurrence that involves a fatality or serious injury, or substantial damage to the aircraft. For occurrences that do not involve a fatality, the determination that the occurrence is an accident can be appealed by writing to the Director, Office of Aviation Safety, NTSB, 490 L'Enfant Plaza, S.W., Washington, D.C. 20594.

INSTRUCTIONS TO PILOTS/OPERATORS FOR COMPLETING THIS FORM

It is necessary that ALL questions on this report be answered completely and accurately.

If more space is needed, continue on a blank sheet of paper.

Nearest City/Place: Use the name of the nearest community in the state where the accident/incident occurred.

Date/Time: Indicate the date and local time of the event. Be sure to indicate the time zone.

Phase of Operation: Indicate the phase of operation during which the accident/incident occurred.

Aircraft Information: Enter aircraft make and model information as indicated on the aircraft registration certificate, including series. If the involved aircraft is certified as "amateur-built," include the name of the producer of the kit or plans, unless an NTSB employee instructs otherwise.

Maximum Gross Weight: Enter the certificated maximum gross weight for the aircraft involved in the occurrence. This should be the same as the maximum gross weight indicated on the aircraft weight and balance documents.

Engine: Enter engine make and model information as indicated on the engine data plate.

The NTSB uses this form for aircraft accident prevention activities and for statistical purposes. NTSB regulations (49 CFR Part 830) require that **ALL** questions be answered completely and accurately. Completion of this form will take approximately 60 minutes. The NTSB does not guarantee the privacy of any information provided in this form. You need not complete this form unless it displays a valid OMB control number, in accordance with 5 C.F.R. § 1320.5(b), which applies to this collection of information.

B. DEFINITIONS

1. "Aircraft Accident" means an occurrence associated with the operation of an aircraft that takes place between the time any person boards the aircraft with the intention of flight and all such persons have disembarked, and in which any person suffers death, or serious injury, or in which the aircraft receives substantial damage. For purposes of this form, the definition of "aircraft accident" includes "unmanned aircraft accident," as defined at 49 CFR 830.2.

2. "Substantial Damage" means damage or failure that adversely affects the structural strength, performance or flight characteristics of the aircraft, and that would normally require major repair or replacement of the affected component. NOTE: Engine failure or damage limited to an engine if only one engine fails or is damaged, bent fairing or cowling, dented skin, small puncture holes in the skin or fabric, ground damage to rotor or propeller blades, and damage to landing gear, wheels, tires, flaps, engine accessories, brakes, or wing tips are not considered "substantial damage" for purposes of this report.

3. "Operator" means any person who causes or authorizes the operation of an aircraft, such as the owner, lessee, or bailee of an aircraft.

4. "Fatal Injury" means any injury that results in death within thirty (30) days of the accident.

5. "Serious Injury" means any injury that (1) requires hospitalization for more than 48 hours, commencing within 7 days from the date the injury was received; (2) results in a fracture of any bone (except simple fracture of fingers, toes, or nose); (3) causes severe hemorrhages, nerve, muscle, or tendon damage; (4) involves injury to any internal organ; or (5) involves second- or third-degree burns, or any burns affecting more than 5 percent of the body surface.

Type of Fire Extinguishing System: If a fire extinguishing system was used to fight an aircraft fire, specify the type(s) of extinguishing system(s) used. Examples include handheld extinguisher, engine fire bottle, cargo/baggage compartment fire suppression system, or airport emergency ground equipment.

Owner/Operator Information: Enter the owner information as shown on the registration certificate. Commercial operators, enter the operator information, including "doing business as" when applicable, as shown on the operator certificate.

Revenue Sightseeing Flight: Indicate whether the accident aircraft was conducting revenue sightseeing operations under 14 CFR Part 91 at the time of the accident.

Air Medical Flight: Indicate whether the accident flight was being conducted for the purpose of carrying medical personnel, patient(s), or organs.

Public Aircraft: Federal, state or local government flight operations such as official travel, law-enforcement, low-level observation, aerial application, firefighting, search and rescue, biological or geological resource management, or aeronautical research. Indicate whether the flight was conducted by the armed forces, federal, state, or local government.

Purpose of Flight: 14 CFR Parts 91, 103, 133, 136, and 137: Indicate the type of operation that was being conducted at the time of the occurrence using the following definitions:

AERIAL APPLICATION--Operations using an aircraft to perform aerial application or dispersion of any substance. Examples include agricultural, health, forestry, cloud seeding, firefighting, insect control, etc.

AERIAL OBSERVATION--These flights include aerial mapping/photography, patrol, search and rescue, hunting, highway traffic advisory, ranching, surveillance, oil and mineral exploration, criminal pursuit, fish spotting, etc.

AIR DROP--Aerial operations, other than aerial application, that are intended to release items in flight.

AIR RACE/SHOW--Includes any flight operations conducted as part of an organized air race or public demonstration.

BUSINESS--includes all personal flying without a paid professional crew for reasons associated with furthering a business, including transportation to and from business meetings or work. This does not include corporate/executive operations, air taxi, or commuter operations.

EXECUTIVE/CORPORATE--Company flying with a paid, professional crew.

FERRY--Non-revenue flight under a special flight or "ferry" permit. Refer to 14 CFR 21.197 for details of special flight permit issuance.

FLIGHT TEST--Flight for the purpose of investigating the flight characteristics of an aircraft/aircraft component or evaluating an applicant for a pilot certificate or rating.

INSTRUCTIONAL--Flying while under the supervision of a flight instructor or receiving air carrier training. Personal proficiency flight operations and personal flight reviews, as required by federal air regulations, are excluded.

OTHER WORK USE--Miscellaneous flight operations conducted for compensation or hire such as construction work (not 14 CFR Part 135 operation), parachuting, aerial advertising, towing gliders, etc.

PERSONAL--Flying for personal reasons (excludes business transportation) including pleasure or personal transportation. This also includes practice or proficiency flights performed under flight instructor supervision and not part of an approved flight training program.

POSITIONING--Non-revenue flight conducted for the primary purpose of relocating the aircraft. Examples include moving the aircraft to a maintenance facility or to load passengers or cargo etc.

UNKNOWN--Use only if the primary purpose of flight is not known.

Other Aircraft--Collision: For all accidents involving a collision with another aircraft, including parked aircraft, check "Collision with other aircraft" under Basic Information and complete this section indicating details about the OTHER aircraft involved in the collision.

Airport Information: Complete this section if the accident/incident occurred on approach, landing, takeoff, departure, or within 3 statute miles of an airport. Please refer to the FAA Airport/Facility Directory or other official source for airport information.

Airport Identifier: Provide the official 3 or 4 character airport identifier number.

Runway: Indicate the number of the runway used, including L, R, or C if applicable.

Runway/Landing Surface: Indicate the type of intended runway/landing surface (do not indicate surface conditions). If the surface type was mixed, check all that apply.

Condition of Runway/Landing Surface: Indicate the condition of the intended runway/landing surface. If multiple conditions existed at the time of the accident, check all that apply.

Weather Information at the Accident/Incident Site: Indicate the weather conditions reported at the accident/incident site at the time of occurrence. If no weather reporting was available for the accident/incident site, indicate the reported conditions at the nearest reporting site. Specify the weather reporting site identifier, the observation time, and distance from the accident/incident.

Sky/Lowest Cloud Condition: Indicate the height above ground level of the lowest cloud condition present at the time of the accident/incident and whether coverage was reported as few, scattered, broken or overcast. Also indicate the height above ground level and coverage of the lowest cloud ceiling present at the time of the accident/incident (reported as broken or overcast).

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs: Describe all NOTAMs (distant (D) or Flight Data Center (FDC), if known), AIRMETs, SIGMETs, and PIREPs in effect near the accident/incident.

Flight Crewmember Information: Indicate the category that best describes the capacity served by this flight crewmember at the time of the accident. The designators "Flight Crewmember 1" and "Flight Crewmember 2" do not refer to a specific pilot position or responsibility. If more than one pilot is aboard, they may be entered in any order and their capacity entered as appropriate.

Degree of Injury: See Definitions on the top half of Page 1 of the instructions. Minor injury is not defined. If an injury does not meet the criteria for another injury category, select Minor.

Date of Last Flight Review or Equivalent: Enter the date of the most recent flight review, or equivalent, completed by this pilot. Refer to 14 CFR 61.56 for accepted equivalents.

Type Ratings: List all type ratings on the pilot certificate. If the pilot holds no type ratings indicate "none." If the pilot holds a pilot certificate other than student and was flying an aircraft requiring an endorsement, enter the type and date of any logbook endorsement(s) for that aircraft. See 14 CFR 61 for examples of required endorsements.

Student Endorsements: If the pilot holds a student pilot certificate, enter all solo endorsements and dates on the student pilot certificate.

Flight Time: Complete the flight time matrix. Solo flight time should be included as "Pilot-in-Command (PIC)" and all dual flight instruction given should be included as "Time as Instructor."

Additional Flight Crewmembers: Complete this section if there were more than two required flight crewmembers on the aircraft. This also includes a check airman performing official duties but does not include cabin crew. State the capacity served by each included crewmember at the time of the accident.

Passenger(s)/Other Personnel: Enter identification and injury severity information for all passengers, cabin crew, and other personnel involved in the accident. See Page 1 of the instructions for the official definition of injury levels.

Several questions throughout the form allow for multiple responses; when appropriate, choose all responses that apply.

These instructions only pertain to major issue areas covered by NTSB Form 6120.1 Pilot/Operator Aircraft Accident/Incident Report. For additional definitions of questions and responses, please refer to www.nts.gov.

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Martinsville State: VA

ZIP: 24112 Country: US

Latitude: 36 deg 37'51"N Longitude: 080 deg 01'06"W

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 10/11/2023 Local Time: 9:30 pm
mm/dd/yyyy

Time Zone: Eastern

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N253BC

Manufacturer: Cirrus

Model: SR22T

Serial Number: 9143

Year of Manufacture: 2023

Amateur-Built: ☐ Yes ☒ No If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

☒ IFR-Equipped and Certified

☐ Commercial Space Flight

☐ Unmanned Aircraft

Maximum Gross Weight: 3600 lbs

Weight at Time of Accident/Incident: 3513 lbs

Number of Seats: 4 Flight Crew Seats: 1

Cabin Crew Seats: _____ Passenger Seats: 3

Number of Engines: 1

Category of Aircraft

- ☒ Airplane
☐ Balloon
☐ Blimp/Dirigible
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift
☐ Rocket
☐ Ultralight
☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☒ Normal
☐ Aerobatic
☐ Balloon
☐ Commuter
☐ Transport
☐ Utility
☐ Restricted
☐ Limited
☐ Provisional
☐ Special Flight
☐ Experimental
☐ Special Light-Sport
☐ Experimental Light-Sport

☐ Certificate of Authorization or Waiver (COA)
☐ None ☐ Unknown

Landing Gear

(Check all that apply)

☐ Retractable

- ☒ Tricycle ☐ Tailwheel
☐ Amphibian ☐ High Skid
☐ Emergency Float ☐ Skid
☐ Float ☐ Ski
☐ Hull ☐ Ski/Wheel
☐ Other Launch/Recovery System
☐ None ☐ Unknown

Engine Type (Select one)

- ☐ Reciprocating ☐ Liquid Rocket
☒ Turbo Shaft ☐ Solid Rocket
☐ Turbo Prop ☐ Hybrid Rocket
☐ Turbo Jet ☐ None
☐ Turbo Fan ☐ Unknown
☐ Electric

Fuel System Type (Reciprocating)

☐ Carburetor ☒ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☐ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	Continental	IO-550	1044938	02/08/2023	315	105	5	
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☒ 100-Hour ☐ Continuous Airworthiness
☐ AAIP ☐ Conditional Inspection
☐ Annual ☐ Unknown

Date Last Inspection: 10/11/2023
mm/dd/yyyy

Airframe Total Time: 121.1 hrs

hours measured at (Select one)

☒ Last Inspection ☐ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☐ Annual
☐ Conditional (Amateur-built only)
☒ Manufacturer's Inspection Program
☐ Other Approved Inspection Program (AAIP)
☐ Continuous Airworthiness
☐ Other, specify: _____

Description of Fire Extinguishing System

- ☐ None
☒ Specify: Fire extinguisher on pilot side floor

Propeller 1

- ☐ Fixed Pitch
☒ Controllable Pitch
☐ Ground Adjustable

Manufacturer: Hartzell

Model: 4C1-F650A1/76C04B-0.6

Propeller 2

- ☐ Fixed Pitch
☐ Controllable Pitch
☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☒ Yes ☐ No

If Yes:

ELT Manufacturer: _____

Model or Part No.: _____

TSO No.: ☐ OC91 (121.5 MHz) ☐ OC91a (121.5 MHz)
☐ OC126 (406 MHz)

Was ELT still mounted in aircraft? ☒ Yes ☐ No

Was ELT still connected to antenna? ☒ Yes ☐ No

Did ELT Activate? ☐ Yes ☒ No

If activated:

Did ELT Aid in Locating Aircraft? ☐ Yes ☒ No

If not activated:

- Indicate Reason: ☐ Impact Damage
☐ Fire Damage
☐ Battery Expired/Damaged
☐ Unknown

Additional Equipment (Check all that apply)

- ☒ ADS-B
☒ Airframe Parachute
☒ Angle of Attack Indicator
☒ Autopilot
☐ Data Recorder
☒ Electronic Flight Bag or Handheld Device
☒ Electronic Multifunction Display
☒ Electronic Primary Flight Display
☐ Handheld GPS
☒ Heads Up Display
☒ Onboard Weather
☐ Satellite Tracking Device
☒ Stall Warning System
☐ Video Recording Device
☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: Brent Keith HollimanCity: EdmondState: OKZIP: 73013Fractional Ownership Aircraft: ☐ Yes ☒ NoCountry: US**Operator of Aircraft**☒ Same As Registered Owner☒ Same Address as Registered OwnerName: Brent Keith HollimanCity: EdmondDoing Business As: Holliman Enterprises, IncState: OKZIP: 73013

Air Carrier/Operator Designator (4 Character Code): _____

Country: US**Operating Certificates Held**

(Check all that apply)

- ☒ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☒ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION** (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)Airport Name: Blue RidgeDistance From Airport Center: 2 smAirport Identifier: KMTVDirection From Airport: 270 degrees trueProximity to Airport: ☒ Off Airport/Airstrip ☐ On Airport/Airstrip ☐ N/AAirport Elevation: 941 ft. msl**Runway Information**Runway ID: 31 (L/R/C) Length: 5002' ft Width: 100' ft**Runway/Landing Surface** (Check all that apply)

- ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☒ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☒ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Aborted Landing (after touchdown)
☐ Crosswind ☐ Unknown

IFR Approach (Check all that apply)

- ☐ None
- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☐ None
- ☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

“Flight Crewmember 1” Responsibilities at the Time of Accident/Incident

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

First Name: Brent

City of Residence: Edmond

Middle Initial: K

State: OK ZIP: 73013

Last Name: Holliman

Country: US

Age at time of Accident/Incident: 57 Date of Birth: [REDACTED] mm/dd/yyyy

Certificate Number: [REDACTED]

Degree of Injury ☒ None ☐ Fatal ☐ Minor ☐ Unknown ☐ Serious	Seat Occupied ☒ Left ☐ Front ☐ Unknown ☐ Right ☐ Rear ☐ Center ☐ Single	Restraint Type Available ☐ None ☐ Lap only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown
Pilot Certificate(s) <i>(Check all that apply)</i> ☐ None ☐ Flight Instructor ☐ Commercial ☐ US Military ☐ Private ☐ Recreational ☐ Airline Transport ☐ Foreign ☐ Student ☐ Sport ☐ Flight Engineer				

Principal Occupation	Medical Certificate	Medical Certificate Validity	Date of Last Medical
☐ Pilot ☒ Other ☐ Unknown	☐ None ☒ Class 3 ☐ Class 1 ☐ Driver's License (Sport Pilot only) ☐ Class 2 ☐ Unknown	☐ Without limitations/waivers ☐ Unknown ☐ With limitations/waivers ☐ N/A ☐ Special Issuance	<u>09/13/2023</u> <i>mm/dd/yyyy</i>

Copy attached

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks: <u>05/18/2023</u> <i>mm/dd/yyyy</i>	Flight Review Aircraft Make: <u>Cirrus</u> Model: <u>SR 22T</u>
---	--

Airplane Rating(s) (Check all that apply)	Other Aircraft Rating(s) (Check all that apply)	Instrument Rating(s) (Check all that apply)	Instructor Rating(s) (Check all that apply)
☐ None ☒ Single-Engine Land ☐ Single-Engine Sea ☐ Multiengine Land ☐ Multiengine Sea	☐ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	☒ None ☐ Airplane ☐ Helicopter ☐ Powered Lift	☐ None ☐ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift ☐ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport

Type Ratings	Student Endorsements <i>(Include dates)</i>
	High Performance

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	758	260	758	0	210	21				
Pilot in Command (PIC)	716	246	716	0	205	21				
Time as Instructor	0	0	0	0	0	0	0			
This Make/Model										
Last 90 Days	55	55	55	55	13	0				
Last 30 Days	18	18	18	18	10	0				
Last 24 Hours	0	0	0	0	0	0				

"FLIGHT CREWMEMBER 2" INFORMATION

"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident

☐ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☒ Other Flight Crew

"Flight Crewmember 2" was pilot flying ☐ Yes ☒ No

"Flight Crewmember 2" Identification

First Name: _____ City of Residence: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____
 Age at time of Accident/Incident: _____ Date of Birth: _____ mm/dd/yyyy
 Certificate Number: _____

Degree of Injury ☐ None ☐ Fatal ☐ Minor ☐ Unknown ☐ Serious	Seat Occupied ☐ Left ☐ Front ☐ Unknown ☐ Right ☐ Rear ☐ Center ☐ Single	Restraint Type <table style="width: 100%;"> <tr> <th style="text-align: left;">Available</th> <th style="text-align: left;">Used</th> </tr> <tr> <td>☐ None</td> <td>☐ None</td> </tr> <tr> <td>☐ Lap only</td> <td>☐ Lap only</td> </tr> <tr> <td>☐ 3-point</td> <td>☐ 3-point</td> </tr> <tr> <td>☐ 4-point</td> <td>☐ 4-point</td> </tr> <tr> <td>☐ 5-point</td> <td>☐ 5-point</td> </tr> <tr> <td>☐ Unknown</td> <td>☐ Unknown</td> </tr> </table>	Available	Used	☐ None	☐ None	☐ Lap only	☐ Lap only	☐ 3-point	☐ 3-point	☐ 4-point	☐ 4-point	☐ 5-point	☐ 5-point	☐ Unknown	☐ Unknown	Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown				
Available	Used																				
☐ None	☐ None																				
☐ Lap only	☐ Lap only																				
☐ 3-point	☐ 3-point																				
☐ 4-point	☐ 4-point																				
☐ 5-point	☐ 5-point																				
☐ Unknown	☐ Unknown																				
Pilot Certificate(s) <i>(Check all that apply)</i> <table style="width: 100%;"> <tr> <td>☐ None</td> <td>☐ Flight Instructor</td> <td>☐ Commercial</td> <td>☐ US Military</td> </tr> <tr> <td>☐ Private</td> <td>☐ Recreational</td> <td>☐ Airline Transport</td> <td>☐ Foreign</td> </tr> <tr> <td>☐ Student</td> <td>☐ Sport</td> <td>☐ Flight Engineer</td> <td></td> </tr> </table>		☐ None	☐ Flight Instructor	☐ Commercial	☐ US Military	☐ Private	☐ Recreational	☐ Airline Transport	☐ Foreign	☐ Student	☐ Sport	☐ Flight Engineer		Medical Certificate <table style="width: 100%;"> <tr> <td>☐ None</td> <td>☐ Class 3</td> </tr> <tr> <td>☐ Class 1</td> <td>☐ Driver's License (Sport Pilot only)</td> </tr> <tr> <td>☐ Class 2</td> <td>☐ Unknown</td> </tr> </table>		☐ None	☐ Class 3	☐ Class 1	☐ Driver's License (Sport Pilot only)	☐ Class 2	☐ Unknown
☐ None	☐ Flight Instructor	☐ Commercial	☐ US Military																		
☐ Private	☐ Recreational	☐ Airline Transport	☐ Foreign																		
☐ Student	☐ Sport	☐ Flight Engineer																			
☐ None	☐ Class 3																				
☐ Class 1	☐ Driver's License (Sport Pilot only)																				
☐ Class 2	☐ Unknown																				
Principal Occupation ☐ Pilot ☐ Other ☐ Unknown		Medical Certificate Validity <table style="width: 100%;"> <tr> <td>☐ Without limitations/waivers</td> <td>☐ Unknown</td> </tr> <tr> <td>☐ With limitations/waivers</td> <td>☐ N/A</td> </tr> <tr> <td>☐ Special Issuance</td> <td></td> </tr> </table>		☐ Without limitations/waivers	☐ Unknown	☐ With limitations/waivers	☐ N/A	☐ Special Issuance													
☐ Without limitations/waivers	☐ Unknown																				
☐ With limitations/waivers	☐ N/A																				
☐ Special Issuance																					
			Date of Last Medical _____ mm/dd/yyyy																		

Medical Certificate Limitations

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks: _____ mm/dd/yyyy

Flight Review Aircraft

Make: _____
Model: _____

Airplane Rating(s) <i>(Check all that apply)</i> ☐ None ☐ Single-Engine Land ☐ Single-Engine Sea ☐ Multiengine Land ☐ Multiengine Sea	Other Aircraft Rating(s) <i>(Check all that apply)</i> ☐ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	Instrument Rating(s) <i>(Check all that apply)</i> ☐ None ☐ Airplane ☐ Helicopter ☐ Powered Lift	Instructor Rating(s) <i>(Check all that apply)</i> <table style="width: 100%;"> <tr> <td> ☐ None ☐ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift </td> <td> ☐ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport </td> </tr> </table>	☐ None ☐ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift	☐ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport
☐ None ☐ Airplane Single-Engine ☐ Airplane Multi-Engine ☐ Gyroplane ☐ Powered Lift	☐ Instrument Airplane ☐ Instrument Helicopter ☐ Helicopter ☐ Glider ☐ Sport				

Type Ratings

Student Endorsements *(Include dates)*

Flight Time <i>(Enter appropriate number of hours in each box)</i>	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time										
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)										
Crew Name and Address					Seat Occupied		Injury			
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown			
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown			
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs							
Crew Name and Address					Seat Occupied		Injury			
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown			
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown			
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs							
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)										
Name and Address			Seat	Injury	Restraint Type		Inflatable Restraints	Age		
First Name: <u>Jamie</u> City : <u>Edmond</u> Middle Initial: <u>D</u> State: <u>OK</u> ZIP: <u>73013</u> Last Name: <u>Holliman</u> Country: <u>US</u> ☐ Crew ☒ Passenger ☐ Other			☐ Left ☐ Center ☒ Right ☐ Unknown Row: _____	☒ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: <u>Tanner</u> City : <u>Elon</u> Middle Initial: <u>G</u> State: <u>NC</u> ZIP: <u>27244</u> Last Name: <u>Holliman</u> Country: <u>US</u> ☐ Crew ☒ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: <u>2</u>	☒ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: <u>Kennedy</u> City : <u>Edmond</u> Middle Initial: <u>A</u> State: <u>OK</u> ZIP: <u>73034</u> Last Name: <u>Roark</u> Country: <u>US</u> ☐ Crew ☒ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: <u>2</u>	☒ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☒ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		☐ Under 5 years If Under 5, ☐ Child Restraint ☐ Lap-Held ☐ Unknown	

FLIGHT ITINERARY INFORMATION

Last Departure Point Airport ID: <u>KMTV</u> City: <u>Martinsville</u> State: <u>VA</u> Country: <u>US</u>	Time of Departure Time: <u>10:15 approx</u> Time Zone: <u>Eastern</u>	Destination Airport ID: <u>KGOK</u> City: <u>Guthrie</u> State: <u>OK</u> Country: <u>US</u>	Type Flight Plan Filed ☒ None ☐ VFR/IFR ☐ Company VFR ☐ IFR ☐ Military VFR ☐ Unknown ☐ VFR Activated? ☐ Yes ☐ No ☐ Unknown
---	--	---	---

Type of ATC Clearance/Service (Check all that apply)

☐ None	☐ Special VFR	☐ Special IFR	☒ VFR Flight Following	☐ Cruise
☐ VFR	☐ IFR	☐ VFR On Top	☐ Traffic Advisory	☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

☐ Class A ☐ Class B ☐ Class C ☐ Class D ☐ Class E	☒ Class G ☐ Demo Area ☐ Warning Area ☐ Prohibited Area ☐ Restricted Area	☐ Military Operations Area (MOA) ☐ Airport Advisory Area ☐ Jet Training Area ☐ TRSA ☐ FAR 93	☐ Special ☐ Air Traffic Control Area ☐ Unknown	Altitude of In-Flight Occurrence: <u>1050</u> ft msl
--	--	---	---	--

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information

(Check all that apply)

☐ National Weather Service	☐ Company
☐ Flight Service Station	☐ Military
☐ TV/Radio	☒ Internet
☒ Automated Report	☐ None
☐ Commercial Weather Service (DUATS)	☐ Unknown
☒ On-Board Weather	

Weather Observation Facility

Facility ID: _____
 Observation Time: _____
 Time Zone: _____
 Distance from Accident Site: _____ nm
 Direction from Accident Site: _____ degrees true

Basic Conditions

☒ VMC
☐ IMC
☐ Unknown

Light Condition

☐ Dawn ☐ Dusk ☒ Dark Night ☐ Unknown
☐ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

☒ Clear ☐ Thin Broken
☐ Few ☐ Thin Overcast
☐ Partial Obscuration ☐ Unknown
☐ Scattered

Lowest Cloud Condition Height

_____ ft agl

Ceiling

☒ None (Clear) ☐ Obscured
☐ Broken ☐ Indefinite
☐ Overcast ☐ Unknown

Ceiling Height

_____ ft agl

Temperature: _____ (C) or 60 (F)

Dew Point: _____ (C) or 48.79 (F)

Altimeter Setting: 28.96 in. Hg
 or _____ MB

Wind Direction

☒ Variable

-or-
Direction: _____ degrees true

Wind Speed

☒ Calm
☐ Light and Variable

-or-
Speed: _____ kts

Wind Gusts

☒ Not Gusting

-or-
Speed: _____ kts

Visibility 10 miles

RVR: _____ feet

RVV: _____ miles

Density Altitude: _____ ft

Intensity of Precipitation

☐ Light
☐ Moderate
☐ Heavy
☐ N/A
☐ Unknown

Type of Precipitation (Check all that apply)

☒ None	☐ Drizzle	☐ Freezing Rain
☐ Rain	☐ Ice Pellets	☐ Snow Shower
☐ Snow	☐ Snow Pellets	☐ Ice Pellets Shower
☐ Hail	☐ Snow Grains	☐ Freezing Drizzle
☐ Rain Showers	☐ Ice Crystals	

Restriction to Visibility (Check all that apply)

☒ None	☐ Fog
☐ Blowing Dust	☐ Ground Fog
☐ Blowing Sand	☐ Haze
☐ Blowing Snow	☐ Ice Fog
☐ Blowing Spray	☐ Smoke
☐ Dust	☐ Unknown

Icing Forecast

Amount	Type
☒ None	☐ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Icing Actual

Amount	Type
☒ None	☐ N/A
☐ Trace	☐ Rime
☐ Light	☐ Clear
☐ Moderate	☐ Mixed
☐ Severe	☐ Unknown
☐ Unknown	

Turbulence

Type (Check all that apply)	Severity
☒ None	☐ Light
☐ Clear Air	☐ Moderate
☐ Terrain-Induced	☐ Severe
☐ Convective Turbulence	☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

None

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☒ Substantial
☐ Minor ☐ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property (Use additional sheet if necessary)

Damage to Right wing substantial. Right main landing gear, Propeller, Windsheild, cowling, nosewheel pant substantial. Minor left wing damage.

NARRATIVE HISTORY OF FLIGHT (Please type or print in ink)

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

The aircraft underwent 100hr inspection 10/8/2023 at Wells Aircraft in Hutchison, Ks. It was delivered back to me on 10/11/2023 that morning. We were scheduled to go and pick up my son from college that afternoon. They reported the crankshaft seal was faulty and it was replaced. They flew the plane back to Guthrie, OK and let me know that I needed to update the avionics.

I went to the airport mid afternoon and fueled the plane, followed by a pre-flight inspection. The avionics were updated and on the ramp, I noticed that the GPS was significantly delayed in picking up location. I cycled the system two times and then all seemed clear. I have not had to do this in the past. We left KGOK (Jamie Holliman, Kennedy Roark, and myself) at around 2:00 pm. Flight went well but I did notice the cylinder head temperature was 399 for cylinder #2 which is the highest I have seen it. I cooled the engine by adjusting mixture and decreasing RPM and that brought the cylinder head temperature down to low 370 range. Otherwise, all was clear. We contacted OKC approach right after departure from KGOK and requested flight following to KBUY (Burlington, NC). The request was granted and instructions recieved and complied with. We diverted to KTKX (Kennett Memorial) for passenger comfort and to re-fuel. We notified ATC at Memphis Center and landed.

Upon landing at KTKX, I cleared the active runway and began to taxi to the FBO. An urgent notification that said Taxiway!! Taxiway!! came on followed by Stall!! Stall!! warnings. We were taxing at 1000-1100 rpm. I had not seen that happen before.

I fueled the aircraft, did an additional preflight walk around and checked the stall warning activator. All checked out. I checked the oil which was at 6 qts. I added 1 qt and the temperature issue resolved and was not an issue after that. (Operating temp of cylinder #2 from that point was between 360-370 at 75% power or 30.5 mm Hg. Manifold pressure.

We contacted Memphis Center and re-established flight following to Burlington with no event.

We picked up my son, went into the city and had dinner. I called 3 times for evening fuel service from Burlington FBO but was never contacted. There was a weather system to the south of us so we decided to go to KMTV (Blue Ridge, VA) for fuel 15 minutes NW. There were three reasons for this. 1. The fuel prices were very reasonable. 2. It was self-service fuel open after hours. 3. It would keep us out of any weather to the south.

We flew into KMTV and enroute, we notified Greensboro approach of our location and intentions and that we would be picking up flight following after fueling. They directed us to maintain VFR, VFR transponder code 1200, and monitor their frequency. I complied. We did a practice RNAV approach for ror runway 31 which was uneventful until the FAF. Vertical navigation worked perfectly but the vertical track at the FAF did not activate. I disengaged the auto pilot and landed without event. We re-fueled and performed an additional walk-around and oil check. All was clear.

I did my run up just off of Runway 31, completed all check lists and had recieved AWOS on 118.45. I preset altitude for terrain and set flight level change to climb at 120kts. We taxied the aircraft into position. Synchronized the heading bug and started our roll.

My routine that I perform on each takeoff is to preset altitude per ATC or desired altitude in uncontrolled space. Set flight level change or climb speed to 120kts and synchronize heading bug so that at 600 ft AGL I can activate autopilot in heading mode to fly runway heading until cleared by ATC or altitude permits to switch to navigation. I did so in this case as well.

Just as we lifted off and developed a positive rate of climb and passed 95 kts, I retracted 50 degrees of flaps and the Primary display blinked off momentarily and reappeared as a large banner saying taxiway. The voice alarm said Taxiway!!! Taxiway!! several times. There was no vertical speed but the airplane appeared to be level. I quickly looked at the display on the MFD and it was completely orange with what appeared to be an auto pilot track turning directly left or south. The plane felt stable and was climbing but displays were showing possible critical attitudes with bank to left and decending. That is all I remember about the displays and altitude reading went off. I just happened to look up and as a practice I always leave my landing lights on at night until well after climb out. It was an extremely dark evening and I looked up quickly and saw that we were flying straight into a large pine tree. It felt as if the autopilot was engaged but I pulled on the yolk and turned hard to the right to avoid a direct hit to the tree. We made sudden and substantial contact with the tree and the plane descended quickly. I was able to get control and somehow get it to climb. The plane was very difficult to control so I was repeatedly hitting the red autopilot disengage button. I could not say for sure that the autopilot was engaged but it did get somewhat easier to control after pushing the button repeatedly. We located the airport and continued to climb. I remember the altimeter coming back on and reading 2200 ft. After turning back to the airport that seemed correct. My wife and I discussed pulling CAPS at that point but due to the unkown terrain, I felt that I could land the plane and had enough altitude at this point. I was concerned that the right main gear may have been destroyed so I landed as lightly as possible on the left main, then nose wheel and let the right down very slowly. The right

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

I am not entirely sure.

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)

Was there Mechanical Malfunction/Failure? ☒ Yes ☐ No
(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

Possible malfunction of the Garmin or system. Possible corrupt update.

**Total Time/Cycles
On Part**

_____ Hours

_____ Cycles

**Time Since This Part
Inspected/Overhauled**

_____ Hours

FUEL & SERVICES INFORMATION

Fuel on Board at Last Takeoff
(Convert from pounds, as necessary)

87 Approximately _____ Gallons

Fuel Type☐ 80/87☐ 115/145☐ Jet B☐ Other, specify _____☒ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive**Other Services, if Any, Prior to Departure**

None

EVACUATION OF AIRCRAFTWas an emergency evacuation of the aircraft performed? ☐ Yes ☒ No**Method of Exit** – Describe how the occupants exited and how many occupants evacuated each location

Normal exit

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)**Aircraft Registration Number**

Manufacturer: _____**Model:** _____**Damage to Other Aircraft**☐ Destroyed☐ Minor☐ Substantial☐ None**Registered Owner of Other Aircraft**

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

10/16/2023

mm/dd/yyyy

Name of Pilot/Operator: Brent Keith Holliman

Signature: _____

-- or -- ☒ Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or -- ☐ Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

ERA24LA007

Reviewed by NTSB Regional Office

AS-ERA

Name of Investigator

Lynn Spencer

Date Report Received

10/16/2023

Complete pilot statement from 6120:

The aircraft underwent 100hr inspection 10/8/2023 at Wells Aircraft in Hutchison, KS. It was delivered back to me on 10/11/2023 that morning. We were scheduled to go and pick up my son from college that afternoon. They reported the crankshaft seal was faulty and it was replaced. They flew the plane back to Guthrie, OK and let me know that I needed to update the avionics.

I went to the airport mid afternoon and fueled the plane, followed by a pre-flight inspection. The avionics were updated and on the ramp, I noticed that the GPS was significantly delayed in picking up location. I cycled the system two times and then all seemed clear. I have not had to do this in the past. We left KGOK (Jamie Holliman, Kennedy Roark, and myself) at around 2:00 pm. Flight went well but I did notice the cylinder head temperature was 399 for cylinder #2 which is the highest I have seen it. I cooled the engine by adjusting mixture and decreasing RPM and that brought the cylinder head temperature down to low 370 range. Otherwise, all was clear. We contacted OKC approach right after departure from KGOK and requested flight following to KBUY (Burlington, NC). The request was granted and instructions received and complied with. We diverted to KTKX (Kennett Memorial) for passenger comfort and to re-fuel. We notified ATC at Memphis Center and landed.

Upon landing at KTKX, I cleared the active runway and began to taxi to the FBO. An urgent notification that said Taxiway!! Taxiway!! came on followed by Stall!! Stall!! warnings. We were taxiing at 1000-1100 rpm. I had not seen that happen before.

I fueled the aircraft, did an additional preflight walk around and checked the stall warning activator. All checked out. I checked the oil which was at 6 qts. I added 1 qt and the temperature issue resolved and was not an issue after that. (Operating temp of cylinder #2 from that point was between 360-370 at 75% power or 30.5 mm Hg Manifold pressure.

We contacted Memphis Center and re-established flight following to Burlington with no event.

We picked up my son, went into the city and had dinner. I called 3 times for evening fuel service from Burlington FBO but was never contacted. There was a weather system to the south of us so we decided to go to KMTV (Blue Ridge, VA) for fuel 15 minutes NW. There were three reasons for this. 1. The fuel prices were very reasonable. 2. It was self-service fuel open after hours. 3. It would keep us out of any weather to the south.

We flew into KMTV and enroute, we notified Greensboro approach of our location and intentions and that we would be picking up flight following after fueling. They directed us to maintain VFR, VFR transponder code 1200, and monitor their frequency. I complied. We did a practice RNAV approach for runway 31 which was uneventful until the FAF. Vertical navigation worked perfectly but the vertical track at the FAF did not activate. I disengaged the auto pilot and landed without event. We re-fueled and performed an additional walk-around and oil check. All was clear.

I did my run up just off of Runway 31, completed all check lists and had received AWOS on 118.45. I preset altitude for terrain and set flight level change to climb at 120kts. We taxied the aircraft into position. Synchronized the heading bug and started our roll.

My routine that I perform on each takeoff is to preset altitude per ATC or desired altitude in uncontrolled space. Set flight level change or climb speed to 120kts and synchronize heading bug so that

at 600 ft AGL I can activate autopilot in heading mode to fly runway heading until cleared by ATC or altitude permits to switch to navigation. I did so in this case as well.

Just as we lifted off and developed a positive rate of climb and passed 95 kts, I retracted 50 degrees of flaps and the Primary display blinked off momentarily and reappeared as a large banner saying taxiway. The voice alarm said Taxiway!!! Taxiway!! several times. There was no vertical speed but the airplane appeared to be level. I quickly looked at the display on the MFD and it was completely orange with what appeared to be an auto pilot track turning directly left or south. The plane felt stable and was climbing but displays were showing possible critical attitudes with bank to left and decending. That is all I remember about the displays and altitude reading went off. I just happened to look up and as a practice I always leave my landing lights on at night until well after climb out. It was an extremely dark evening and I looked up quickly and saw that we were flying straight into a large pine tree. It felt as if the autopilot was engaged but I pulled on the yolk and turned hard to the right to avoid a direct hit to the tree. We made sudden and substantial contact with the tree and the plane descended quickly. I was able to get control and somehow get it to climb. The plane was very difficult to control so I was repeatedly hitting the red autopilot disengage button. I could not say for sure that the autopilot was engaged but it did get somewhat easier to control after pushing the button repeatedly. We located the airport and continued to climb. I remember the altimeter coming back on and reading 2200 ft. After turning back to the airport that seemed correct. My wife and I discussed pulling CAPS at that point but due to the unkown terrain, I felt that I could land the plane and had enough altitude at this point. I was concerned that the right main gear may have been destroyed so I landed as lightly as possible on the left main, then nose wheel and let the right down very slowly. The right main was still intact but tire was not inflated. I experienced a slight pull to the right but was able to clear the runway to the left and exited the plane. All passengers were fine with no injuries. I immediately called 911 and the airport was an EMSA station and an EMSA helicopter landed very shortly afterward and contacted the airport manager.

I spoke with Cirrus, the State Police, and a representative of the FAA that evening. I called the NTSB the following day to report the accident.