



Photo 1 – Photo From NTSB Duty Officer. Left Side View of the Inverted Airplane Where it Came to Rest. Note the Structural Damage to the Vertical Stabilizer.