



Todd Gunther
Senior Air Safety Investigator
Office of Aviation Safety - Eastern Region

Date: September 18, 2025

Subject: Broward County Aviation Department (BCAD) Report

The BCAD prepared a report describing the initial response to the accident involving N1953Y. According to the report, the responding agencies included the Pembroke Pines Fire Department, Station 33. After the accident, an engineer with Truck 33 accessed the airplane and moved the master and fuel selector switches in addition to the fuel mixture and propeller feathering levers. These actions were subsequently communicated to personnel who responded from the local FAA FSDO.