

Dear Hugo,

11/13/2023

On November 11, 2023, approximately at 2:50pm eastern, I departed Runway 10 enroute to Fort Lauderdale. After lining up for departure, I set the power & started the takeoff roll. Upon rotation, I pitched up to transition to the climb; however, I then realized my airspeed was starting to decrease as well as my altitude. I then put gear down but realized I was not going to have enough runway if I waited for the gear to extend & lock. Thus, the landing resulted in a skid down the runway until coming to a full stop on the runway. It was my belief I got into a microburst on takeoff so I made the decision to put the plane back on the ground at Lake City Airport.

Certificate number: [REDACTED]

Total flight time: 1,341 hrs

Josh Palacios,

[REDACTED] 11/13/2023