



Investigator Name
Title
Division

Date: 11/20/2023

Subject: ERA24LA042, FAA Statement

Contact: Marco Alvarado, FAA inspector

During a telephone discussion with inspector Alvarado, we reviewed the accident photos. It was determined that the helicopter sustained substantial damage to the main rotors and the tail boom. An examination of the engine, drivetrain, and flight controls did not reveal any anomalies. A review of the maintenance logbook excerpts did not reveal any anomalies. Inspector Alvarado said that the pilot reported that he did not have any mechanical issues with the helicopter prior to the accident.