



Photo 1 – View of Damaged Left Vertical Stabilizer (VSP)



Photo 2 – View of Damaged Vertical Stabilizer Facing Direction of M/R Rotation (VSP)



Photo 3 - View of Damaged Vertical Stabilizer Facing Opposite Direction of M/R Rotation (VSP)