

ERA24LA054

INVESTIGATION PHOTOGRAPHS



Photo 1: View of the airplane at the accident site (Photo Courtesy FAA)



Photo 2: View of the fuel selector as observed at the accident site (Selected, Left Tip) (Photo Courtesy FAA)




Photo 3: Placard located in the cockpit.




Photo 4: View of the fuel selector valve.



Photo 5: View of the left main tank separated from the wing, with no leaks observed upon filling with water.



Photo 6: View of the registration number.