



Kurt Gibson
Aviation Accident Investigator
Office of Aviation Safety, Eastern Region

Date: 03/20/2024

Subject: ERA24LA113

Contact: James Holmes - FAA Inspector

The following is a summary of a phone interview with Mr James Holmes:

The FAA inspector reported that during his initial examination of the airplane, the landing lights were tested on N650FT and were found to operate normally. The inspector also reported that he inspected the intersection of Runway 9R and taxiway Q at MLB and found that the taxiway center line paint was clearly visible and the taxi line went to the runway centerline.

#END#