

ERA24LA152

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View of the airplane at the accident site (Courtesy of FAA)



Photograph 2 - View of the airplane at the accident site (Courtesy of FAA)



Photograph 3 - View of contamination found in the fuel servo. (Courtesy of Lycoming)