



U.S. Department
of Transportation
**Federal Aviation
Administration**

South Florida Flight Standards District Office 19
2895SW 145th Avenue Suite 120
Miramar, FL 33027

Juan C Garcia - Inspectors Statement – Accident Investigation

NTSB: ERA24LA153

ATQA:

Event No.:

SAS PTRS No.:

Task ID:

Experimental Operating Amateur Built Aircraft Registration: N291AG

Builder: Denzil Velarde

Model: MTO Sport

Serial No: MoO1280

ATT: 523 Hours

When: March 24, 2024

Where: Tavernaero Park Airport (PVT Field) FA81

What: Part 91 Experimental Operating Amateur Built Aircraft Registration N291AG, serial number M01280 with one pilot and one passenger on board attempting to taking off from Tavernaero Park Airport (PVT Field) FA81 runway 026 crashed at the end of runway 026 into a concrete retaining wall. Both pilot and passenger sustain minor injuries, aircraft destroyed. N291AG is registered to N291AG CO, [REDACTED] 19801.

PIC Pilot:

SCHALKOORT, BOB KLASS
[REDACTED]

Cert. No. [REDACTED]

Medical Certificate: None

Phone: [REDACTED]

E-mail: [REDACTED]

Passenger: Wayne Hipscotch

PIC Interview statement:

Pilot stated he and his friend were taking off from runway 026 and the wind was shifting around a lot, but it was more of a crosswind. Pilot stated, they took off lifting off but was not climbing fast enough and unable to maintain airspeed and altitude, so he decided to attempt land on the remaining runway but ran out of time and room so attempted to land on crossroad but fell short crashing. Pilot stated engine was at full power with no issues with the engine power he just did not have enough airspeed at liftoff and the wing might have shifted to a tail wind.

Examination of the aircraft and maintenance issue:

The aircraft rear empennage section impacted concrete retraining airport boundary wall.

Juan C Garcia
Aviation Safety Inspector /FAA IIC

