

ERA24LA159


INVESTIGATIVE PHOTOS



Photograph 1 - View of engine



Photograph 2 - Engine view from rear



Photograph 3 - Rocker Arms and springs, (Note: lack of oil)