

MEMORANDUM FOR RECORD

Timothy W. Monville
Sr. Air Safety Investigator
Office of Aviation Safety-Eastern Region

Date: March 12, 2026

Subject: ERA24LA164

As part of the investigation, the engine compartment fuel supply hoses were retained and submitted to the NTSB Materials Laboratory for examination. The pictures of the hoses are documented below:



Figure 1 All Hoses As Received




Figure 2 Hose Segment 1 Bisected



Figure 3 Hose Segment 2 Bisected



Figure 4 Hose Segment 3 Bisected



Figure 5 Hose Segment 4 Bisected