



Ryan Enders
Aviation Accident Investigator
Eastern Region

Date: May 15, 2024

Subject: ERA24LA165 Garmin Data

Two SD memory cards were retrieved from the airplane with the data pulled by the FAA party coordinator. The raw files were sent to Ryan Enders.

Review of the last moments of the accident flight show wind speeds of 11-13.4 knots from the 359-360 direction during the accident events. A screenshot from the Garmin data is below.

[illegible]