



Investigator Name: Brian Rayner
Title: Sr. ASI
Division: ERA

Subject: ERA24LA191

Contact: Dr. Paul Chelminski

According to Dr. Chelminski, the airplane was "rolling" and "tobogganing...as if we were descending a hill on the snow" during the final approach. He said the airplane touched down twice, after which the pilot appeared to "turn and roll the airplane left as if to take off again." Dr. Chelminski added that the pilot made no announcements, and that there was no communication between them from runway contact to the accident site. He said that in the bank, "it felt as if the plane lost power" but that he couldn't detect if the engine had stopped.