



Ralph E. Hicks
Senior Air Safety Investigator
AS-ERA

Date: 5/21/2024

Subject: ERA24LA197, Correction to NTSB Form 6120.1

The pilot, Mr. David Stiles, incorrectly reported on his NTSB Form 6120.1 that the engine type was a Continental IO-550. Mr. Stiles confirmed that the actual engine type was a Continental E-225-8.