



Photo 1 – View of helicopter with severed tail boom



Photo 2 – View of severed tail rotor