

ERA24LA205

AIRWORTHINESS

Group Chair's Factual Report - Attachment 4
N413JM 12-month inspection checklist dated April 4, 2024

12 M

MSM 05-21-02

 Modified content

REFERENCE

Documentary Unit	MSM 05-21-02
References/Effectivity	12 M
Language	EN(en)
Issue Date	2023.05.22

EFFECTIVITY

Model	AS350
Version	B3
Serial Number	

STATUS

Type of modification	R
Description	
Reason for update	
Maintenance work affected	

ATA 24 - ELECTRICAL POWER

24 - 31 BATTERY

Task Number Description/Remarks	Documentation	Margin	Initial
24/31/00/000/000/060 Battery 150CH-1 (7050A4243027) Check. DI Effectivity : B3 Unchanged	AMM 24-33-00_6-2	35 D	N/A 

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

24/31/00/000/000/065

Battery[AMM 24-33-00_6-2](#)

36 D

151CH-1

(7050A4243040)

N/A

Check.

DI

Effectivity : B2,B3

Unchanged

CONCORD R6-390E INSTALLED.

ATA 25 - EQUIPMENTS AND FURNISHINGS**25 - 00 EQUIPMENT AND FURNISHING**

Task Number

Description/Remarks

[Documentation](#)

Margin

Initial

25/00/00/000/000/015

Belt and harness - Strap[AMM 25-20-00_5-1](#)

36 D

[AMM 25-20-00_5-1](#)

Check and functional test.

Operation to be carried out each 12 M (margin 36D) or after each installation of the seat or of the harness.

DI/FT

Effectivity : B2,B3

Unchanged

25 - 10 COCKPIT

Task Number

Description/Remarks

[Documentation](#)

Margin

Initial

25/10/40/000/000/000

APPAREO camera[AMM 25-10-40_5-2](#)

36 D

Functional test.

FT

Effectivity : B2,B3

Unchanged

25 - 66 EMERGENCY LOCATOR TRANSMITTER (ELT)

Task Number

Description/Remarks

[Documentation](#)

Margin

Initial

25/66/20/000/000/020

Emergency locator transmitter[AMM 25-66-20_6-1](#)

36 D

KANNAD INTEGRA AP-H (ER)

Installation check.

DIJFT

Effectivity : B2,B3

Unchanged

S1854501-01

25/66/34/000/000/030

Emergency locator transmitter[AMM 25-66-02_6-1](#)

36 D

KANNAD 406 AF.

KANNAD 121 AF-H.

KANNAD 406 AF-H.

Installation check.

DIJFT

Effectivity : B2,B3

Unchanged

S1854501-02 NOT INSTALLED.

N/A

ATA 26 - FIRE PROTECTION**26 - 22 OPT - EXTINGUISHER, FIRE, CABIN**

Task Number

[Documentation](#)

Margin

Initial

Description/Remarks

26/22/01/000/000/020

Cabin fire extinguisher[AMM 26-21-00_6-2](#)

36 D

[12085-01](#)[\(S262A10T1001\)](#)[PLA863520-00](#)[\(T262M50T0002\)](#)

Weighing.

Interval starting from the date of manufacture.

WGH

Effectivity : B2,B3

Unchanged

ATA 34 - NAVIGATION**34 - 25 GYRO HORIZON**

Task Number

[Documentation](#)

Margin

Initial

Description/Remarks

Printed from ORION H125 - AS350 B2-B3 Rev.018.00 (Update 03) MSM 05-21-02 (2023-06-25)

Printed by z00000073554 on 2023-09-05 12:13:30

B3

https://orion.airbus.com/pub/as350-b2b3_018-00_en-en/018.00.03/du/DMC-AS350-B3-0000-05-21-02-00000-000S-S_en-EN/fulltext/default

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

34/25/00/000/000/030	
Calibration battery GI 275	
AMM 34-25-32, 5-2	36 D
010-01912-80 (704A47331111)	
FT	
Effectivity : B3	
Changed	

Mechanist	Date 04APR2024	Inspector	Date 04APR2024
Name :	Signature :	Name :	Signature :
Jason E. Phillips		Jason E. Phillips	

© Copyright - Airbus

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK !!
ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION