

Joshua Young
Air Safety Investigator
AS-ERA

Date: 5/5/2025

Subject: ERA24LA211, Engine Age Question for Owner

Contact: Frank Neilson, Owner

Mr. Neilson was contacted via electronic mail by the IIC on 1 May 2025, following a conversation on the telephone about the age of his airplane's engine and the exceedance of the manufacturers' recommended time between overhaul. The following was asked by the IIC:

"Just following up on this and want to confirm whether you did or did not receive notice from the maintenance shop about the age of your airplane's engine and the fact that it was 15 years past the manufacturer's recommended time between overhaul?"

Mr. Neilson responded via electronic mail on 5 May 2025 with the following:

"No sir we never received any notice or information regarding that statement. He continued to complete annuals and never once mentioned the aircrafts engine being outside manufacturers recommended time between overhaul. You mentioning it is the first time I am ever hearing that information."