

Joshua Young
Air Safety Investigator
AS-ERA

Date: 6/7/2024

Subject: ERA24LA211, FAA Follow Up Inspection

Contact: Ricardo Rodriguez, Aviation Safety Inspector, Federal Aviation Administration

The following was sent to the IIC via electronic mail detailing the follow up examination performed on June 6, 2024 by FAA Inspector Rodriguez.

"06/06/2024

Visited aircraft location which was a private hangar on the owner's property to follow up on the Invstg. under the direction of NSTB IIC, Mr. Young. The aircraft was quarantined on the owner's property at the suggestion of NTSB IIC and never relocated and quarantined at Aircraft Engineering Inc. as originally planned on 05/08/2024.

Performance of compression check which indicated engine compression, removed fuel injector lines from fuel spider valve for the failed cylinders, #2, #3, #4 & #5, no debris/obstructions noted. Removed fuel inlet hose to fuel spider valve, no debris/obstructions noted. Partially removed lower engine cowling, performed a total engine visual inspection, no anomalies, non-accident-related damages found, will send pics from yesterday visit shortly."