

ERA24LA222

## INVESTIGATION PHOTOGRAPHS



**Photograph 1 - View of airplane in field showing damage to the wings and fuselage. (FAA Photo)**



**Photograph 2 - View of No. 4 connecting rod protruding to the top of the case. (FAA Photo)**