



Investigator Name: Leah D. Read
Title: Sr. ASI
Division: ERA

Date: May 29, 2024

Subject: ERA24LA231

Contact: Rick J. Brown, Principal Maintenance Inspector, Orlando FAA/FSDO

Inspector Brown performed a test-run of the engine. He stated the engine started immediately and all engine parameters were in the "green." No mechanical deficiencies were noted that would have precluded normal operation of the engine. Inspector Brown removed the oil temperature probe, which was tested by the operator under his guidance. The oil probe tested within normal range.

Data from the onboard G-1000 was also downloaded and provided to the FAA per NTSB request.