

Aircraft Record General Information

Manufacturer Piper Model PA-25-235

Serial 25-5168 Registration Number N 8715L

Date of Manufacture _____

Engine(s) currently installed:

Manufacturer _____ Model _____ Serial _____

Manufacturer _____ Model _____ Serial _____

Propeller(s) currently installed:

Manufacturer _____ Model _____

HUB Model _____ Serial _____ Serial _____

Blade Model _____ Serial _____ Serial _____ Serial _____

Blade Model _____ Serial _____ Serial _____ Serial _____

DATE to 2021	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
24 MAR.	3455.0		12168.0	Serviced aircraft in accordance with mfg. inspection checklist, comply AD 76-07-12 OK good, comply AD 77-21-06 visual inspect of tube cluster OK good. AD's verified to issue 2021-07. I certify that this aircraft has been inspected in accordance with an <u>Annual</u> inspection and is determined to be in airworthy condition.
2022				
25 Apr.	3619.0		12332.0	Serviced aircraft in accordance with mfg. inspection checklist. Comply AD 76-07-12 OK OK good, comply AD 77-21-06 visual inspection of tube cluster - OK good.

DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2022				
25 Apr.	3619,0		12,332,0	AO's verified to issue 2022-08. I certify that this aircraft has been inspected in accordance with an <u>Annual</u> inspection and is determined to be in airworthy condition. [Redacted Signature] [Redacted Signature]
April 14	3650		12,363.0	Replaced Battery w/ New Concord RG-35AXC SN 41202394. No change in w/B [Redacted Signature] Owner App [Redacted Signature]
July 4	3790		12,503.0	Engine Failure Occured, OH Reprid. Removed eng. for Core to Send to Lycoming. July 20, 2023

DATE 2023 40 2025	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
Dec 1	3790		12,503	Installed Factory Remanufactured Engine S/N RL-26040-40E. Replaced all oil hoses w/ New hose. Installed Upper and Lower oil cooler with O/H'd coolers from Pacific Oil Cooler Service. Installed O/H'd Alternator P/N ALX-6520R S/N- P6310092. Installed and timed Left and Right Mags O/H'd by Aircraft Accessories of Oklahoma Inc. or "Remaned" by TCM. Right Mag- P/N BL34930-1 S/N F17IA244R. Left Mag- P/N 10-349290-1 S/N A265292. Installed New "Shower of Sparks" P/N 10-176487-122M. New Engine Mounts installed. all work performed in accordance with

DATE 2023 10	RECORDING TAGH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
				Lycoming Installation Checklist and Service Instructions #1070AB. Inspected all cables, pulleys, control surfaces, hinges, brakes, wheels, Newtires and hubs and serviced all according to Piper Pawnee Service manual. For [REDACTED] [REDACTED]
11 Dec	3790.0		12503.0	Serviced aircraft in accordance with mfg. inspection checklist, comply AD 76-07-12 ops ck good, comply AD 77-21-06 visual inspect of rear tube cluster ck good. AD's verified to issue 2023-25.

continue next page →

DATE	RECORDING TACH TIME	TODAY'S FLIGHT	TOTAL TIME IN SERVICE	Description of Inspections, Tests, Repairs and Alterations Entries must be endorsed with Name, Rating and Certificate Number of Technician or Repair Facility. (See back pages for other specific entries.)
2023				
11 Dec	3740.0		12503.0	I certify that this aircraft has been inspected in accordance with an <u>Annual</u> inspection and is determined to be in airworthy condition.
2024	3943.2		12,656	Aircraft + Engine involve in accident this Date.
June 5				