

Accident report on June 8 at Jamestown municipal Airport – 2A1

At 10:26 AM on June 8 plane number N155LT was landing runway one. Weather conditions are as follows 3 mph from the southwest gust at 9 mph. The plane started rocking left and right just above the runway, approximately 20 to 30 feet. The pilot attempted to land the plane making hard contact with the ground. I called 911 at 10:26 AM. The canopy hatch would not open two people inside with the cockpit filled with white smoke. I broke open the canopy on the pilot side of the plane to get the people out. Everyone was OK. First responder showed up. Roger Norris assistant, chief of police was on scene and took a police report. A radio call went out to close the airport and all runways. The airport reopened at 12:15 PM after the runway was inspected for any debris or hazards. The plane was then loaded with a rollback to hanger number two lock was installed on the door waiting FAA inspection.

[REDACTED]

[REDACTED]