



Eric Alleyne
Air Safety investigator
AS-Eastern Region Aviation

Date: 6/18/2024

Subject: ERA24LA260

Contact: Joaquim Neto, PIC, review of statement

The PIC was interviewed to review his statement after the 6120 was received.

The pilot clarified that when he "cut" the power the airplane landed hard on the runway and directional control was lost. The airplane veered off the runway and collided with a ditch about 80 feet off the runway.