

ERA24LA263

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Aft forward view of helicopter damage. (Courtesy of Pilot/Owner)



Photograph 2 - Helicopter damage as it rests in the ditch. (Courtesy of Pilot/Owner)



Photograph 3 - Tail rotor drive belt jam nut out of position. (Courtesy of Pilot/Owner)



Photograph 4 - Side view of the tail rotor drive belt jam nut out of position. (Courtesy of Pilot/Owner)



**Photograph 5 - Helicopter during recovery. Note the damage to the rotor blades and tail boom.
(Courtesy of Pilot/Owner)**