



Investigator Name: Leah D. Read
Title: Sr. ASI
Division: ERA

Date: March 10, 2026

Subject: Correspondence with Earl Wright

Between July 2024 and January 2025, several attempts were made to have Mr. Wright complete and submit the NTSB 6120.1 form; however, a completed form was never submitted. In addition, since Mr. Wright recovered the airplane to his property and initially provided requested photographs of the fractured propeller for the NTSB to review. The quality of these photographs were insufficient to determine a reason as to why the blade failed, so more detailed photos were requested several times. No new photos were submitted at the time the NTSB report was written.