



Investigator Name: Leah D. Read
Title: Sr. ASI
Division: ERA

Date: November 12, 2024
Subject: ERA24LA343
Contact: Phillipe Larivee, BOS FAA/FSDO

Inspector Larivee spoke with Mr. Pace on the day of the accident and later via telephone. Inspector Larivee said the pilot stated the following on both occasions:

"...Mr. Pace said he had just purchased the aircraft in Chatham MA a few hours earlier. He was flying the aircraft home to VA when he began to have a rough running engine. Mr. Pace said there is no mixture control, so he began to adjust the throttle. He stated he found a "sweet spot" which he felt would maintain flight to OQU. He did say he was aware of and was advised of a crossing tail wind on runway 5 but chose to land that runway anyway. Mr. Pace stated he had no recollection of what happened after initial touch down."