

ERA24LA357

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Accident horizontal stabilizer damage (Courtesy of FAA)



Photograph 2 - accident elevator damage (Courtesy of FAA)