


ERA24LA376

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Landing gear switch wiring (Courtesy of FAA)



Photograph 2 - Chafed gear switch wires (Courtesy of FAA)



Photograph 3 - Lower fuselage accident damage (Courtesy of FAA)