

Joshua Young  
Air Safety Investigator  
AS-ERA

**Date:** December 19, 2024

**Subject:** ERA25FA020, Pilot's Neighbor Interview

**Contact:** Don Anderson, Pilot's Neighbor

Mr. Anderson was interviewed via telephone, and the following is a summary of that interview:

- He reported that the pilot was having some issues with cylinder head temperatures so the passenger, who was also an A&P mechanic, went with him to the air race to check the temperatures.
- He reported that the pilot had been having difficulty with the Garmin GPS unit and he had recently had the GPS antenna changed.
- The airplane had been having some electrical issues, and the passenger had previously repaired the avionics power switch. The airplane also had a boost pump failure in the past.