



Joshua Young
Air Safety Investigator
AS-ERA

Date: 10/21/2024

Subject: ERA25FA020, OR1 Fuel Records

Contact: Don Flynn, Airport Manager, Atmore Municipal Airport (OR1)

Mr. Flynn was contacted by phone and subsequently by electronic mail by the IIC to inquire if the accident aircraft N510G purchased fuel when they stopped at OR1 on 10/20/2024, the day of the accident flight. He responded the same day with the following:

"William G. Mahler purchased 24.13 gallons of 100LL at 12:13 pm.

The fire chief and I both watched the plane leave the fuel area and depart the airport. There were no indications of anything wrong with the way the engine was running. The aircraft did back taxi to allow the full 5,100 ft of runway.

The fuel guy working the ramp said all of last weeks samples were clean, the right color and contained no water.

If I can do anything else let me know.

Don Flynn"