

ERA25LA007

INVESTIGATION PHOTOGRAPHS




Photograph 1 - Accident site (Courtesy of FAA)




Photograph 2 - Thermally destroyed fuselage (NTSB)




Photograph 3 - Thermally separated nose section (NTSB)



Photograph 4 - Thermal damage noted to the fuel selector valve (NTSB)



Photograph 5 - Fuel pressure regulator and check valve (NTSB)



Photograph 6 - Thermal damage noted to hydraulic lines (NTSB)