

"FLIGHT CREWMEMBER 2" INFORMATION**"Flight Crewmember 2" Responsibilities at the Time of Accident/Incident**

☐ Captain ☐ First Officer ☒ Pilot ☐ Co-Pilot ☐ Student Pilot ☐ Flight Instructor ☐ Check Pilot ☐ Flight Engineer ☐ Other Flight Crew

"Flight Crewmember 2" was pilot flying ☐ Yes ☒ No

"Flight Crewmember 2" Identification

First Name: Dwayne

City of Residence: Louisville

Middle Initial: A

State: KY ZIP: 40216

Last Name: Johnson

Country: U.S.

Age at time of Accident/Incident: 23

Date of Birth: [REDACTED] (mm/dd/yyyy)

Certificate Num [REDACTED]

Degree of Injury

☒ None ☐ Serious
☐ Unknown ☐ Fatal
☐ Minor

Seat Occupied

☒ Left ☐ Front ☐ Unknown
☐ Right ☐ Rear
☐ Center ☐ Single

Restraint Type**Available**

☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☒ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☐ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☒ Unknown

Supplemental Restraint, specify: _____

Pilot Certificate(s) (Check all that apply)

☐ None ☒ Flight Instructor ☒ Commercial
☐ US Military ☐ Private ☐ Recreational
☐ Airline Transport ☐ Foreign ☐ Sport
☐ Student ☐ Flight Engineer

Principal Occupation

☒ Pilot
☐ Other
☐ Unknown

Medical Certificate

☐ None ☐ Class 3 ☐ Unknown
☒ Class 1 ☐ BasicMed
☐ Class 2 ☐ Driver's License (Sport Pilot Only)

Medical Certificate Validity

☒ Without limitations/avaivers ☐ Unknown
☐ With limitations/avaivers ☐ N/A
☐ Special Issuance

Date of Last Medical

07/24/2023
mm/dd/yyyy

Medical Certificate Limitations**Medical Certificate Special Limitations****Personal Flight Equipment (Check all that apply)**

☐ Fire resistant flight suit ☐ Helmet ☐ Laser protective visor/glasses ☐ Personal Locator Beacon(s) (PLB) ☐ Fire resistant gloves
☐ Helmet visor ☐ Night vision goggles ☐ Personal flotation ☐ Other: _____

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

mm dd/yyyy

Flight Review Aircraft

Make: _____

Model: _____

Airplane Rating(s)

(Check all that apply)

☒ Single-Engine Land
☐ Single-Engine Sea
☒ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s)

(Check all that apply)

☒ None
☐ Airship
☐ Balloon
☐ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s)

(Check all that apply)

☐ None
☒ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s)

(Check all that apply)

☐ None ☐ Instrument Airplane
☒ Airplane Single-Engine ☐ Instrument Helicopter
☐ Airplane Multiengine ☐ Helicopter
☐ Gyroplane ☐ Glider
☐ Powered lift ☐ Sport

Type Ratings and Applicable Logbook Endorsements**Student Endorsements (Include dates)**

Flight Time (Enter hours for each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air	Multi-engine Rotorcraft	Tail-wheel
						Actual	Simulated					
Total Time	482.4	10.0	459.4	17.3	48.8	2.7	57.4					
Pilot in Command (PIC)	407.4	10.0	397.6	4.6	40.0	2.7	53.0					
Time as Instructor	119.1		119.1									
This Make/Model												
Last 90 Days	72.8	.7	72.8									
Last 30 Days	22.1	.7	22.1									
Last 24 Hours	3.1	.7	3.1									

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☐ None ☐ Substantial
☐ Minor ☐ Destroyed
 ☐ Unknown

Aircraft Fire

- ☐ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☐ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown


Description of Damage to Aircraft and Other Property (*Use additional sheet, if necessary.*)

NARRATIVE HISTORY OF FLIGHT (*Please type or print in ink.*)

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

Crew member 2

During the approach to landing, on short final, I noticed and announced that the airspeed was lower than recommended approach speed. After this was announced, a go-around procedure was attempted but unsuccessful. During the go-around attempt, the aircraft had a hard touchdown. The aircraft then started to climb and we decided to attempt another approach and landing. The next landing was successful and the flight came to an end.



11/6/24

OPERATOR/OWNER SAFETY RECOMMENDATION (*How could this accident/incident have been prevented?*)

Crew Member 2

This accident may have been prevented if the go-around procedure was completed successfully. More familiarity and training with the aircraft was needed.



11/6/24