

ERA25LA040

FOLLOW UP EXAM PHOTOGRAPHS



Photograph 1 - Cable damage to stabilizer. (NTSB)



Photograph 2 - Cable striation marks in stabilizer. (NTSB)