

ERA25LA054

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Airplane postaccident (Courtesy of Pilot)



Photograph 2 - Right main landing gear postaccident (Courtesy of Pilot)



Photograph 3 - Main landing gear attachment end (Courtesy of Pilot)



**Photograph 4 - Postaccident damaged landing gear attach plate with bolt half
(Courtesy of FAA)**



Photograph 5 - Right main landing gear attach bolt half (Courtesy of Pilot)



Photograph 6 - Postaccident damaged landing gear attach bracket and lower wing strut attach fitting (Courtesy of Pilot)



Photograph 7 - Gear leg retention bracket bolt with locknut threads (Courtesy of FAA)