



Lucas Winn
Aviation Accident Investigator
Aviation Safety, Eastern Region

Date: December 11, 2024

Subject: ERA25LA068, Accident Video Description

A video was obtained from On the Scene News via Facebook showing A Diamond DA-42NG, N508PA landing with the right main landing gear still retracted. It shows the right wing settle to the runway and the airplane turning to the right, exiting the runway and striking a taxiway sign, resulting in the landing gear falling out of the well and damage to the right wing.