



Joshua Young
Air Safety Investigator
AS-ERA

Date: 2/25/2025

Subject: ERA25LA079, Questions for recovery crew

Contact: Florida Air Recovery

During the wreckage examination the IIC asked the recovery crew if they had cut any of the zip ties inside the empennage of the airplane. They reported that they did not. They continued, stating that they removed the aft most empennage panel and upon seeing cargo inside the empennage area they replaced the panel and did not open any other panels.